212-200-0052

Senttle, WA 208-223-8007 Any Arbor, Mi 313-865-6610

San Watso, CA 416-570-5401

404-111-000

910-207-1427

Residen, TX 71**3 686 888**8



REDACTED VERSION

Ecology & Environment, Inc. 11550 Newcastle Ave. #250 Baton Rouge, LA 70816

Tuesday, March 18, 1997

Ref Number: 1X97836

POLARIZED LIGHT MICROSCOPY (PLM)

Project: 020601 WESTBANK ASBESTOS

SAMPLE	LOCATION	APPEARANCE	SAMPLÉ TREATMENT	ASBES %	TOS TYPE	%	<u>NONASB</u> FIBROUS	estos %	NONFIBROUS
WB\$509G03B	(h) (6)	Brown	Teased	< 1% Chrys	sotile	ŀ	,	100%	6 Other
		Fibraus Homogenéous	: 	<u></u>		<u>.</u>			
WBS209G01		Brown Fibrous Homogeneous	Teased	2% Chrys 4 1% Crock		·		989	6 Other
WBS209G02		Brown Fibrous Homogeneous	Teased	2% Chry < 1% Croc			,	989	% Other
WBS3271328G 01		Brown Fibrous Homogeneous	Teased	< 1% Chry	sotil a			100	% Other
WBS3271328G 02		Brown Fibrous Homogeneous	Teased	< 1% Chry	sotile		· · · · · · · · · · · · · · · · · · ·	1 00 1	,: % Other
WBS3271328G 03		Brown Fibrous Homogeneous	Teased	< 1% Chry	sotile	r i		100	% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Arthur Hernandez, Jr **Analyst**

004377

Approved Signatory

1



Discriminars: PLM has been known to miss sebestos in a small percentage of samples which contain sabestos. Thus negative PLM results cannot be guaranteed. Floor tites and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim produce endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and snelyze tayered samples.